



For welding. With collar.  
*A souder. A collerette.*  
*Para soldar. Con cuello.*

SS 316

13 13 510 70 33

16 16 510 70 34

19 19 510 70 35

25 25 510 70 36

32 32 510 70 37

38 38 510 70 38

51 51 510 70 39

63 63 510 70 40

75 76 510 70 41

102 102 510 70 42